Weather Conditions (Temp/Wind Speed/Dire	une 15, 2023 Time of Arrival: 10am Time of Departure: 12:30 PM iam {Billy} Carnes ERM, Randy Broussard [westlake] /Wind Speed/Direction, etc.): 87* party cloudy WSW 8 to 10 mph									A construction of the second sec
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Cavern Well 2	Cavern Well 2A	CL-19	CL-97,8,12,13,14	CL-15,16	
(location description):				(near BW-22, west side of Central Lake)				(Central Lake bubbling site)	(Central Lake Bubbling site)	
No boat ride today not able to check Bubbling sites in Central Lake ERM is using the boat for sampling.		• •	Fluid in cellar lower					No bubbling seen	No bubbling seen	
		able to see any bubbling	than bubbling train 284 gpm	last inspection			Still have a small bubbling train	today at those locations	today at those Locations.	
Photos taken? (save to F: drive)	no		no	no						
Tubing Pressure (if applicable)	175		78		230	1.17				
Casing Pressure (if applicable)	174		433		476					
Bubbling?				yes			yes			
Sheen?				yes			no			
Oil?				yes			no			
Odor?				yes			no			
Any new remedial work?				no			no			
Any impact to vegetation?				no			no			
Any impact to wildlife?				no			no			