Proce of constitution

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location: Sulphur Mines Dome

Date: Thursday, June 22, 2023 Time of Arrival: 10:50 AM Time of Departure: 12:10 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, Randy Broussard, Control Room Personnel

Weather Conditions (Temp/Wind Speed/Direction, etc.): 86 Degrees, Partly Cloudy, Wind ESE at 8 mph

Any planned work for today: Check pressures and observe bubbling locations

Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL 11-16	Location 9 (Water location	Yellow Rock Wells	Boardwalk SWDs		Flowlines
(location description):				side of Central	(east side of Central		Two SWDs and One			(all brine and oil
				Lake)	Lake)		Production			flowlines)
		Pad is dry; no	Inj rate 301.4 gpm; Water level in cellar is low, so no	Sorbent boom has been replaced	Only one small bubble location noted near the	Same bubbling locations and intensity (minor intensity) as noted during past inspections. Water		SN 973458 Rig on location, no pressures; SN 973459 tbg -9, csg 129.3 (tbg is on		
		bubbling	bubbling is visible	recently.	bulkhead	in area is very low.	tbg - 30, csg - 45	vacuum)		
Photos taken? (save to F: drive)	No	No	No	No	No	Yes				
Tubing Pressure (if applicable)	192.8	N/A	71.1	N/A	N/A	N/A				
Casing Pressure (if applicable)	172.7	N/A	428.9	N/A	N/A	N/A				
Bubbling?	No	No	No	Yes	Yes	Yes				
Sheen?	No	No	No	Yes	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	Yes	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				