INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, June 26, 2023 Time of Arrival: 9:10 AM Time of Departure: 12:30 PM Inspector Name(s): William (Billy) Carnes Other personnel on site: Airboat Captain, Randy Broussard [Westlake] Weather Conditions (Temp/Wind Speed/Direction, etc.): 88* to 91* Partly Cloudy SW 8 mph Any planned work for today: Check Bubbling site's with Airboat in Central Lake & Crystal Lake Check Cavern Well Pressures & some Yellowrock Well Pressure's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central	CL-3,4,5,6,17,18 (Central Lake	CL-21,22,19 (Central Lake	CL-7,8,9,12,13 (Central Lake	CL-14,15 & 16 (Central Lake	Yellowrock	Crystal Lake
				Lake)	bubbling site)	bubbling site)	bubbling site)	bubbling site)		North Bank side
On the Airboat Ride this morning I observed NO new bubbling sites in Central Lake & Crystal Lake. Operator has a Workover Rig on Cavern well # 21		Well Pad dry not able to see any bubbling spots	292 gpm	Operator changed boom out and has a new oil boom set	-	Still bubbling - No changes from last inspection	No bubbling observed like in Passed inspections	No bubbling observed like passed inspections	S-7 140psi Tubing S-4 0psi Tubing # 1012 25psi Tubing & casing	On Inspection I observed NO bubbling sites in Crystal Lake @ time of inspection
Photos taken? (save to F: drive)				no	no	no	No	no	no	no
Tubing Pressure (if applicable)	173		80							
Casing Pressure (if applicable)	175		441							
Bubbling?				yes	yes	yes				
Sheen?				yes	no	no				
Oil?				yes	no	no				
Odor?				yes	no	no				
Any new remedial work?				no	no	no				
Any impact to vegetation?				no	no	no				
Any impact to wildlife?				no	no	no				