

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Thursday, June 29, 2023 Time of Arrival: 11:45 AM Time of Departure: 1:30 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, Control Room Personnel

Weather Conditions (Temp/Wind Speed/Direction, etc.): 91 Degrees, Sunny, Wind SW at 6 MPH

Any planned work for today: Check pressures and observe bubbling locations



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL 11-16		Yellow Rock Wells	Cavern Well 2	Flowlines
(location description):				(near BW-22, west		(Water location		1	
				side of Central	1,	between PPG 2 and			(all brine and oil
				Lake)	Lake)	PPG 4)	Production		flowlines)
		Pad is dry; no bubbling	Water level in cellar is low, so no	•	Only one small bubble location noted near the	intensity (minor intensity) as noted			
Photos taken? (save to F: drive)	No	No	No	No	No	Yes	.,.,		
Tubing Pressure (if applicable)	N/A	N/A		N/A	N/A	N/A		219.7	
Casing Pressure (if applicable)	172.9	N/A	436.3	N/A	N/A	N/A		322.6	
Bubbling?	No	No	No	Yes	Yes	Yes			
Sheen?	No	No	No	Yes	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			