

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Time of Departure:

Location: Sulphur Mines Dome

Date: Thursday, July 6, 2023

11:45 AM

1:00 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, Control Room Personnel

Weather Conditions (Temp/Wind Speed/Direction, etc.): 89 Degrees, Sunny, Wind S at 3 MPH

Time of Arrival:

Any planned work for today: Check pressures and observe bubbling locations

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL 11-16	Location 9	Yellow Rock Wells	Cavern Well 2	Flowlines
(location description):				(near BW-22, west		(Water location			
				side of Central	1.	between PPG 2 and			(all brine and oil
				Lake)	Lake)	PPG 4)	Production		flowlines)
		Pad is dry; no bubbling	Inj rate 293 gpm; Water level in cellar is low, so no bubbling is visible	Oil contained by sorbent boom. Sorbent boom has been replaced recently. Water is very low.	Only one small bubble location noted near the bulkhead	Same bubbling locations and intensity (minor intensity) as noted during past inspections. Water in area is very low.	SN 110159 (SWD) tbg - 150, csg - 0; SN 109963 (SWD) tbg - 0, csg - 95; SN 209459 (Producer) tbg - 40 csg - 55		
Photos taken? (save to F: drive)	No	No	No	No	No	Yes	10,000 00		
Tubing Pressure (if applicable)	N/A	N/A	77.01	N/A	N/A	N/A		214.41	
Casing Pressure (if applicable)	173.2	N/A	436.7	N/A	N/A	N/A		533.63	
Bubbling?	No	No	No	Yes	Yes	Yes			
Sheen?	No	No	No	Yes	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			