	Time of Arrival: rgne [Westlake] Airb	oat captain	INJE B	INSPECTIO FFICE OF COI CTION & MII 617 NORTH ATON ROUG	NSERVATION NING DIVISIO 3RD STREET 5E, LA 70802					
Weather Conditions (Temp/Wind Speed/Direction, etc.): 86* to 90* Mostly Cloudy W 9 mph Any planned work for today: Airboat ride in Central lake & Crystal lake check bubbling site's & normal Cavern Inspections, bubbling sites.										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	Cavern well 2	Cavern Well 2a	CL- 1	CL-3,4,5,6,17,21,2	CL-6,7,8,9,12,13	CL-14,15,16,19	CRL-1
							(Central Lake bubbling site)	(Central Lake bubbling site)	(Central Lake bubbling site)	Crystal Lake
On inspections today I observed a possible small bubbling site in Chystal lake. N 30* 15' 7.84" W 93* 25' 1.53" Lot of the bubbling sites in Central lake have stopped bubbling or they are the same or less intense.		Pad dry	298 gpm			No changes since last Mondays Inspection	Still bubbling, the bubbling seem to be the same as last Monday's Inspection.	I oberved these passed bubbling sites not bubbling today.	I observed these passed bubbling sites not active today.	Might or Might not be a bubbling site in a area of concern.
Photos taken? (save to F: drive)						No				
Tubing Pressure (if applicable)	173		218	218	0.93					
Casing Pressure (if applicable)			435	328						
Bubbling?						yes	yes			yes
Sheen?						yes	no			no
Oil?						yes	no			no
Odor?						yes	no			no
Any new remedial work?						no	no			no
Any impact to vegetation?						no	no			no
Any impact to wildlife?						no	no			no
			1	1	1	1	1	1	1	1