INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802										FILE Harding Hardin
Date: Thursday, July 13, 2023 Time of Arrival: 9:30 AM				Time of Departure: 12:30 PM					RW, No. 22	C A A
Inspector Name(s): William [Billy] Carnes									ANTERN LAN	
	ussard [Westlake] Va								RW No 2 A 2A	Annual M
Weather Conditions (Temp/Wind Speed/Direction, etc.): 88* to 91* Mostly Cloudy SW 12mph										
Any planned work for today:									A Carlos Andrea	
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central	CL-8,12,15 (Central Lake	CL-13,14 (Central Lake	Site 9 on map	Site 19 on map	Yellowrock	
					bubbling site)	bubbling site)	Along main road	Along main road		
Operator going to move Oil out of the 7b cavern to frac tanks in field. No Boat ride today so some of the bubbling spots will not be inspected by the state rep. today.				No changes since	l observed no	l observed no	I observed no		# 1012 25psi tubing	
				last inspection on 7-		bubbling from the	bubbling from the	small bubbling train	S-7 140 psi tubing	
		Pad dry	296 gph	10-2023	bank	bank	bank	still active	S-4 0 psi tubing	
Photos taken? (save to F: drive)				no				no		
Tubing Pressure (if applicable)	173		75							
Casing Pressure (if applicable)			433							
Bubbling?				yes				yes		
Sheen?				yes				no		
Oil?				yes				no		
Odor? Any new remedial work?				yes				no		
				no				no		
Any impact to vegetation? Any impact to wildlife?				no				no		