

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, July 17, 2023 Time of Arrival: 9:20 AM Time of Departure: 12:30 PM

Inspector Name(s): William [Billy] Carnes

Other personnel on site: Kevin LaVergne [Westlake] Richard [Stan's Airboats] Vance Hill {Yellowrock}

Weather Conditions (Temp/Wind Speed/Direction, etc.): 85* to 91* Sunny WSW 4 mph

Any planned work for today: Check bubbling site's, Cavern Wells Pressures & some Yellowrock Field Wells pressures [tubing & casing]



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-3,5,6,17,18,21	CL-7,8,9,12,13,14	CL-15,16,19	Yellowrock	
(location description):				(near BW-22, west side of Central	(Central Lake	(Central Lake	(Central Lake		
				Lake)	1,		bubbling site)		
				Lukey	bubbling site)	bubbling site)	bubbling site)		
On Inspection today I observed that the bubbling site CRT # 1 in Crystal Lake was not bubbling @ time of inspection, may have not been anything before, will keep checking to see if there's any changes. A lot of the bubbling site's aroung the area are not as intense as before or not bubbling anymore. Will keep checking those site's when the Airboat is available.		Pad Dry	306 gpm injecting into Cavern. Fluid level in Well cellar is high enough to see the small bubbling train along side of Wells casing.		These site's still have bubbling activity happening like past Inspections.	No bubbling activity today during inspection.		# 1012 25psi tubing S-7 160psi tubing S-4 0psi tubing	
Photos taken? (save to F: drive)									
Tubing Pressure (if applicable)	174		78 psi						
Casing Pressure (if applicable)			427 psi						
Bubbling?			yes	yes	yes				
Sheen?			no	yes	no				
Oil?			no	yes	no				
Odor?			no	yes	no				
Any new remedial work?			no	no	no				
Any impact to vegetation?			no	no	no				
Any impact to wildlife?			no	no	no				