

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Thursday, July 20, 2023 Time of Arrival: 11:10 AM Time of Departure: 12:15 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: K Lavergne, R Broussard, Control Room Personnel

Weather Conditions (Temp/Wind Speed/Direction, etc.): 89 Degrees, Partly Cloudy, Wind SW at 5 MPH

Any planned work for today: Check pressures and observe bubbling locations



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B		CL 11-16	Location 9	Yellow Rock Wells	Cavern Well 2		Flowlines
(location description):				(near BW-22, west side of Central	least side of Control	(Water location between PPG 2 and	Two SWDs and One			(all brine and oil
				Lake)	Lake)		Production			flowlines)
		Pad is dry; no	Inj rate 307 gpm; Minor bubbling	Oil contained by sorbent boom. Sorbent boom has been replaced	Only one small bubble location noted near the	Water in area is very low. Very few bubbling locations	SN 110159 (SWD) tbg -160, csg -0; SN 109963 (SWD) tbg - 0, csg -90; SN 209459 (Producer)			
		bubbling	alongside casing.	very low.	bulkhead	bubbling.	tbg - 30, csg - 50			
Photos taken? (save to F: drive)	No	No	No	No	No	Yes				
Tubing Pressure (if applicable)	N/A	N/A	74.5	N/A	N/A	N/A		228.6		
Casing Pressure (if applicable)	175.2	N/A	431.3	N/A	N/A	N/A		456.1		
Bubbling?	No	No	No	Yes	Yes	Yes				
Sheen?	No	No	No	Yes	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	Yes	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				