

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



## Location: Sulphur Mines Dome

Date: Thursday, July 27, 2023 Time of Arrival: 10:00 AM Time of Departure: 1:15 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J Bradley, R Broussard, Control Room Personnel, ERM, Lonquist, Sonic Surveys

Weather Conditions (Temp/Wind Speed/Direction, etc.): 88 Degrees, Partly Cloudy, Winds Light and Variable

Any planned work for today: Check pressures/observe bubbling locations; Witness collection of brine sample from 7B

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL 11-16	Location 9	Yellow Rock Wells	Cavern Well 2	Flowlines
(location description):				(near BW-22, west		(Water location			
				side of Central	(east side of Central				(all brine and oil
				Lake)	Lake)	PPG 4)	Production		flowlines)
		Pad is dry; no bubbling	0	Oil contained by sorbent boom. Sorbent boom has been replaced recently. Water is very low.	Only one small bubble location noted near the bulkhead		SN 110159 (SWD) tbg - 160, csg - 0; SN 109963 (SWD) tbg - 0, csg - 90; SN 209459 (Producer) tbg - 30, csg - 50		
Photos taken? (save to F: drive)	No	No	No	No	No	No			
Tubing Pressure (if applicable)	N/A	N/A	71.3	N/A	N/A	N/A		227.3	
Casing Pressure (if applicable)	181.8	N/A	429.8	N/A	N/A	N/A		367.5	
Bubbling?	No	No	No	Yes	Yes	Yes			
Sheen?	No	No	No	Yes	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			