Location: Sulphur Mines Dome Date: Monday, August 14, 2023	Time of Arrival:	8:4!	INJI	INSPECTIO OFFICE OF COL ECTION & MI 617 NORTH BATON ROUG	NSERVATION NING DIVISIO 3RD STREET <u>5E, LA 70802</u>	ON				FILE File F
Inspector Name(s): Billy Carnes										
Other personnel on site: Randy Broussard [Westlake] Richard - Stan's Airboat Captain										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 85 * to 90 * Sunny/HOT W 8 mph										
Any planned work for today: Ride Airboat to Inspect bubbling site's on the water, check Well Pressure's & other bubbling site's on land										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-5,22,6,3 & 24	Central Lake	Cavern Well #2	Cavern Well #2a	Yellowrock	
(location description):				(near BW-22, west side of Central	(Central Lake bubbling site)	Central Lake		Cavern wen #2a		
Westlake is supposedly selling oil today. No other Issue's today										
		Well pad is dry so can't see any bubbling	256 gpm injection rate		These bubbling site's were active today	All other known bubbling site's weren't active today.			#1012 55 psi tubing S-7 170 psi tubing S-4 0 psi tubing	
Photos taken? (save to F: drive)				no	no					
Tubing Pressure (if applicable)	191		93				221 psi	1.19 psi		
Casing Pressure (if applicable)			449							
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					