Surface of the second	INT OF REAL
	CONSERVICE A

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Thursday, August 17, 2023 Time of Arrival: 11:00 AM Time of Departure: 12:55 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: K. Lavergne, R. Broussard, Control Room Personnel

Weather Conditions (Temp/Wind Speed/Direction, etc.): 89 Degrees, Sunny, Winds SW at 3 mph

Any planned work for today: Check pressures/observe bubbling locations

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL 11-16	Location 9	Yellow Rock Wells	Cavern Well 2	Flowlines
(location description):				(near BW-22, west		(Water location			
				side of Central	(east side of Central	between PPG 2 and	Two SWDs and One		(all brine and oil
				Lake)	Lake)	PPG 4)	Production		flowlines)
		Pad is dry; no bubbling	Inj rate is 280 gpm; Constant Injection Rate test is ongoing	sorbent boom.		Area is dry. No bubbling.	SN 110159 (SWD) tbg - 170, csg - 0; SN 109963 (SWD) tbg - 0, csg - 90; SN 209459 (Producer) tbg - 33, csg - 50		
Photos taken? (save to F: drive)	No	No	No	No	No	No			
Tubing Pressure (if applicable)	N/A	N/A	51.5	N/A	N/A	N/A		224.7	
Casing Pressure (if applicable)	191.5	N/A	379.5	N/A	N/A	N/A		782.3	
Bubbling?	No	No	No	Yes	Yes	No			
Sheen?	No	No	No	Yes	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			