

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location: Sulphur Mines Dome

Date: Monday, August 21, 2023 Time of Arrival: 8:45 AM Time of Departure: 11:45 PM

Inspector Name(s): William [Billy] Carnes

Other personnel on site: Randy Broussard, Josh Bradley [Westlake] Richard w/Stan's Airboat

Weather Conditions (Temp/Wind Speed/Direction, etc.): 88* to 92* sunny [HOT] NE 13 mph

Any planned work for today: Ride Airboat in Central Lake, SaltLake & the pond behind Cavern Well 7b. Also check bubbling site's & some Cavern well pressure's along with some Yell

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-2	CL-3,4,5,6,17	CL-18,21 & 24		Yellowrock Wells	
(location description):				(near BW-22, west						
				side of Central	(east side of Central		(Central Lake	(Central Lake		
				Lake)	Lake)	bubbling site)	bubbling site)	bubbling site)		
Westlake had some equipment today that was clearing some brush out of the way so that the Pond & area behind Cavern Well 7b can be inspected for any anomalies.										
		Well pad dry not able to see bubbling	283 gpm injection	Fluid level is low in this location due to drought		On inspection I observed bubbling @ those locations	On Inspection I observed bubbling @ those locations.	All other bubbling site's on Central Lake bubbling map weren't bubbling on inspection today.	#1012 46 psi tubing S-7 170 psi tubing S-4 0 psi tubing	
Photos taken? (save to F: drive)				no		no	no			
Tubing Pressure (if applicable)	189 psi		48 psi							
Casing Pressure (if applicable)			368 psi							
Bubbling?				yes		yes	yes			
Sheen?				yes		no	no			
Oil?				yes		no	no			
Odor?				yes		no	no			
Any new remedial work?				no		no	no			
Any impact to vegetation?				no		no	no			
Any impact to wildlife?				no		no	no			