	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802									State St
Location: Sulphur Mines Dome Date: Thursday, August 24, 2023 Time of Arrival: 11:10 AM Time of Departure: 12:30 PM Inspector Name(s): Bily Carnes Other personnel on site: Randy Broussard [Westlake] Weather Conditions (Temp/Wind Speed/Direction, etc.): 95* to 97* Sunny N1 mph Any planned work for today:										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	Central Lake	Cavern Well 2	Cavern Well 2a	Yellowrock		
				side of Central Lake)		(Central Lake bubbling site)		(Central Lake bubbling site)		
NONE					Due to the drought the bubbling site's that are not in			#1012 45 psi tubing		
				Fluid level in hole is	Central Lake are			S-4 0 psi tubing		
		Pad dry	301 GPM	low due to drought	not visable			S-7 170 psi tubing		
Photos taken? (save to F: drive)				no						
Tubing Pressure (if applicable)	184 psi		61 psi			231 psi	0.89 psi			
Casing Pressure (if applicable)			420 psi			811 psi				
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						