INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, August 28, 2023 Time of Arrival: n/a Time of Departure: n/a Inspector Name(s): Billy Carnes Other personnel on site: DeAnn Chapman, Randy Broussard [Westlake] Richard/Airboat Captain 78* to 80 * Party Cloudy N7 mph light rain @ times										
Any planned work for today: Check bubbling site's in Central Lake, Dome area also Well pressure's on some Cavern Wells & some of Yellowrock's wells										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-3,4,5,6,18,21,2 Central Lake bubbling site's	Central Lake (Central Lake bubbling site)	Cavern Well 2	Cavern Well2a	Yellowrock	Flowlines (all brine and oil flowlines)
Lonquest has a Eline unit on Yellowrocks Well # 969 to take Fluid samples		Pad dry	306 gpm injection	Fluid in hole low due to drought	These are still have active bubbling	On inspection I observed that the other marked bubbling site's in Central Lake were not active @ time of inspection			#1012 45 psi tubing S-7 170 psi tubing S-4 0 psi tubing	
Photos taken? (save to F: drive)				no						
Tubing Pressure (if applicable)	183 psi		68 psi				234 psi	0.74 psi		
Casing Pressure (if applicable)			424 psi				820 psi			
Bubbling?				yes					-	
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						