		INSPECTION FORM OFFICE OF CONSERVATION ECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802						A constant of the second		
Weather Conditions (Temp/Wind Speed,	ey, K. Lavergne, R. Brou	ssard, Control Room 93 Degrees, Sunny,		Time of Departure	: 1:4	5 PM				
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A		CL-1 (near BW-22, west	CL 11-16	Location 9 (Water location	Yellow Rock Wells	Cavern Well 2		Flowlines
				side of Central Lake)	(east side of Central Lake)		Two SWDs and One Production			(all brine and oil flowlines)
		Pad is dry; no bubbling	Inj rate is 306 gpm	Oil contained by sorbent boom. Water is very low.	Water level is very low and small bubbling location near the bulkhead is barely visible due to algae. Brown substance (possibly brown algae) is mixed in with green algae.	Area is dry. No bubbling.	SN 110159 (SWD) tbg - 175, csg - 0; SN 109963 (SWD) tbg - 0, csg - 90; SN 209459 (Producer) tbg - 30, csg - 50			
Photos taken? (save to F: drive)	No	No	No	No	Yes	No				
Tubing Pressure (if applicable)	N/A	N/A		N/A	N/A	N/A		236.7		
Casing Pressure (if applicable)	183.6	N/A	427.6		N/A	N/A		822.4		
Bubbling?	No	No	No	Yes	Yes	No				
Sheen?	No	No	No	Yes	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	Yes	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				