INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Tuesday, September 5, 2023 Time of Arrival: 9;00 am Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard, Kevin LaVergne [Westlake] & Airboat Captain fron Stan's Airboat// NOTE SEE BELOW IN GENERAL COMMENTS Weather Conditions (Temp/Wind Speed/Direction, etc.): 83* to 89* Sunny SSE 12 mph Any planned work for today:										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-2 (east side of Central Lake)	Central Lake (Central Lake bubbling site)	Cavern Well 2	Cavern Well 2a	Yellowrock	
General Comments: Their was a General Inspection @ the Sulpur Mines Dome with Representatives from DNR/I&M div., WestLake & other Cavern Operators. . Note:Westlake had a Brine fluid spill by the Pig catching slab & some of the fluid flowed into Central Lake, Spill looked like less than a Barrel of Brine Fluid. Westlake Represtative stated that they had call it in		Pad dry	233 gpm	Fluid level is low due to the drought	Westlake had a small brine spill out of the Pig catching slab that some of the run off got into Central Lake. Less than 1 bbl	The I&M Div. representatives rode in the Airboat today in central Lake.			#1012 50psi tubing S-7 170psi tubing S-4 0psi tubing	
Photos taken? (save to F: drive)				no	no					
Tubing Pressure (if applicable)	183 psi		73 psi				241 psi	1.09 psi		
Casing Pressure (if applicable)			434 psi				828 psi			
Bubbling? Sheen?				yes yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						