Location: Sulphur Mines Dome			INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802						Enternant Barrier Barier Barri
Weather Conditions (Temp/Wind Speed/E	ne, Control Room Per	sonnel, TRIAD Person 92 Degrees, Sunny,	15 AM nel Wind WSW at 9 mph	Time of Departure	: 12:4	10 PM			
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL 11-16	Location 9	Yellow Rock Wells	Cavern Well 2	Flowlines
(location description):				(near BW-22, west side of Central Lake)	(east side of Central Lake)	(Water location between PPG 2 and PPG 4)	Two SWDs and One Production		(all brine and oil flowlines)
		Pad is dry; no bubbling	Inj rate is 251.1 gpm	Oil contained by sorbent boom. Water is very low.	Water level is very low. Minimal intermittent bubbling near the bulkhead.	Area is dry. No bubbling.	SN 110159 (SWD) tbg - 175, csg - 0; SN 109963 (SWD) tbg - 0, csg - 90; SN 209459 (Producer) tbg - 30, csg - 60		
Photos taken? (save to F: drive)	No	No	No	No	No	No			
Tubing Pressure (if applicable)	N/A	N/A	66.82		N/A	N/A		243.1	
Casing Pressure (if applicable)	182.6	N/A	429.4	,	N/A	N/A		831.2	
Bubbling?	No	No	No	Yes	Yes	No			
Sheen?	No	No	No	No	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			