

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Thursday, September 14, 2023 Time of Arrival: 11:30 AM Time of Departure: 12:50 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: J. Bradley, R. Broussard, K. Lavergne, Control Room Personnel

Weather Conditions (Temp/Wind Speed/Direction, etc.): 83 Degrees, Overcast, Wind S at 2 mph

Any planned work for today: Check pressures/observe bubbling locations

Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	(near BW-22, west	CL 11-16	Location 9 (Water location	Yellow Rock Wells		Flowlines
				side of Central Lake)	(east side of Central Lake)	between PPG 2 and PPG 4)	Two SWDs and One Production		(all brine and oil flowlines)
		Pad is dry; no bubbling	Inj rate is 253 gpm; Minor bubbling alongside casing	Oil contained by sorbent boom.			SN 110159 (SWD) tbg -175, csg - 0; SN 109963 (SWD) tbg - 0, csg - 85; SN 209459 (Producer) tbg - 40, csg - 60		,
Photos taken? (save to F: drive)	No	No	No	No	No	No			
Tubing Pressure (if applicable)	N/A	N/A	71.2	N/A	N/A	N/A		224.6	
Casing Pressure (if applicable)	180.7	N/A	429.4	N/A	N/A	N/A		782.3	
Bubbling?	No	No	Yes	Yes	Yes	No			
Sheen?	No	No	No	No	No	No			
Oil?	No	No	No	Yes	No	No			
Odor?	No	No	No	Yes	No	No			
Any new remedial work?	No	No	No	No	No	No			
Any impact to vegetation?	No	No	No	No	No	No			
Any impact to wildlife?	No	No	No	No	No	No			