INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Thursday, October 19, 2023 Time of Arrival: 11:15 AM Time of Departure: 12:50 PM Inspector Name(s): Sarah Hitchcock Other personnel on site: J. Bradley, R. Broussard, K. Lavergne, Control Room Personnel, Turner Industries Weather Conditions (Temp/Wind Speed/Direction, etc.): 80 Degrees, Sunny, Wind SW at 7 mph Any planned work for today: Check pressures/observe bubbling locations										 A series A series<
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL 11-16 (east side of Central Lake)	Location 9 (Water location between PPG 2 and PPG 4)	Yellow Rock Wells Two SWDs and One Production	Cavern Well 2	Central Lake (Central Lake Bubbling Locations)	Flowlines (all brine and oil flowlines)
	Snubbing Unit on well. Pressure from Control Room.	Pad is dry.	Inj rate is 317.7 gpm; Minor bubbling alongside casing	Oil contained by sorbent boom. Boom has been replaced recently.		Two distinct bubbling locations noted. Additional minimal bubbling may be present, but is hard to discern due to wind and vegetation.	SN 110159 (SWD) tbg - 175, csg - 0; SN 109963 (SWD) tbg - 0, csg - 85; SN 209459 (Producer) tbg - 30, csg - 60		No airboat ops today	
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	N/A	N/A	67.6			N/A		249.1		
Casing Pressure (if applicable)	175	N/A	429.7	N/A	N/A	N/A		373.5		
Bubbling?	No	No	Yes	Yes	Yes	Yes				
Sheen?	No	No	No	No	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	No	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				