NI OF	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION							19852	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
									16 10	
								LINE NO. 0		EW. No. 20
				617 NORTH 3RD STREET				A State of S	200	Table N. SN 25665 973661 N. (LALSN
BATON ROUGE, LA 70802								and the second second		And Manage Start
Location: Sulphur Mines Dome										
Date: Monday, October 23, 2023	Time of Arrival:	0.00	) AM	Time of Departure:	1.0	0 PM		A CONTRACTOR OF THE	AT A A A A A A A A A A A A A A A A A A	
Inspector Name(s): Billy Carnes	Time of Arrival.	5.00	AM	Time of Departure.	1.0		1.3			Solar V
•	chard [airboat operat	orl Randy Broussard	[Westlake] Vance Hi	ll [Vellowrock]					100000 771266 (24) BW/ No. 2 A 2A	
Other personnel on site: Captain Richard [airboat operator] Randy Broussard [Westlake] Vance Hill [Yellowrock]   Weather Conditions (Temp/Wind Speed/Direction, etc.): 85* clear skies 8 to 12 mph winds ESE										
Any planned work for today: Check Bubbling Site's Check Pressure's on some Cavern Wells & some Yellow Rock Wells										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	Cavern Well 4	Cavern Well 2a	Cavern Well 2	CL- 3,4,5,6,9,18,21	,24	Yellowrock
(location description):				side of Central				(Central Lake		
				Lake)				bubbling site)	L	
On Inspection I Observed that the bubbling site's didn't have any significant changes on										
this Inspection from my last inspection last month. Westlake is										
working on Cavern 6x today. [see										
Westlake's report from today to see what										
they did to Well]	Onereteruseling			Still bubbling & it				These are the site's that I observed		#1012 50 pai tubina
	Operator working on Well . No data to			looked like Westlake changed				bubbling today		#1012 50 psi tubing S-7 180 psi tubing
	report.	Pad dry	318 gpm injecting	booms				during Inspection.		S-4 0 psi on tubing
Photos taken? (save to F: drive)				no						
Tubing Pressure (if applicable)			69 psi		258 psi	6.95 psi	382 psi			
Casing Pressure (if applicable)			432 psi		250 psi		252 psi			
Bubbling?			yes	yes				yes		
Sheen?			no	yes				no		
Oil?			no	yes				no		
Odor?			no	yes				no		
Any new remedial work?			no	no				no		
Any impact to vegetation?			no	no				no		
Any impact to wildlife?			no	no				no	ļ	
									ļ	
									1	