INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802											
Location: Sulphur Mines Dome Date: Monday, October 30, 2023 Inspector Name(s): Billy Carnes	Time of Arrival:	9:1	5 AM	Time of Departure: 1:00 PM					All (16, 22)		
•	ichard[ w/Airboat] Jos rection, etc.):	sh Bradley {Westlake] 54* Windy & Cloudy		ock] Kevin Lavergne [\	WestLake]						
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 4	Cavern Well 2	Cavern Well 2a	CL-3,4,5,6,9,17,18 (Central Lake bubbling site)	,24	Yellowrock	
Westlake has ERM coming today to get Brine water samples & Westlake Rep. stated that they were finished working on Cavern 6x.								These Bubbling			
	Snubbing Unit still on Well	Pad dry not able to inspect bubbling	314 gpm injection	No change since last inspection done on 10/23/2023	2			sites on the map today were active all others were inactive today @ time of inspection		#1012 40 psi tubing S-7 180 psi tubing S-4 0 psi tubing	
Photos taken? (save to F: drive)			no	No							
Tubing Pressure (if applicable)			69 psi		250 psi	253 psi	9.0 psi				
Casing Pressure (if applicable)			431 psi			388 psi					
Bubbling?			yes	yes				yes			
Sheen?			no	yes				no			
Oil?			no	yes				no			
Odor?			no	yes				no			
Any new remedial work?			no	no				no			
Any impact to vegetation?			no	no				no			
Any impact to wildlife?			no	no				no			
1	1	1	1	1	1	1	1	1	1	1	