Weather Conditions (Temp/Wind Speed/Dire	2023 Time of Arrival: 9:00 AM Time of Departure: 11:30 AM sh Bradley [Westlake] Captain Richard [Airboat skipper] Vance Hill [Yellowrock]										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Central Lake (Central Lake bubbling site)	Yellowrock			
Dome activity today was just general operating, no oil or gas removed today or any Cavern Well workover.		Pad dry not able to see bubbling	320 gpm injection	Bubbling look the same as passed inspections			Bubblings site's 3,4,5,6,9,24 were active today @ time of inspection. All other bubbling	#1012 45 psi tubing S-7 180psi tubing S-4 0 psi tubing			
Photos taken? (save to F: drive)	no		no	no	no						
Tubing Pressure (if applicable)	165 psi		73 psi		258 psi	11.4					
Casing Pressure (if applicable)			433 psi		397 psi						
Bubbling?				yes							
Sheen?				yes							
Oil?				yes							
Odor?				yes							
Any new remedial work?				no							
Any impact to vegetation?				no							
Any impact to wildlife?				no							