Location: Sulphur Mines Dome			INJ I	ECTION & MI 617 NORTH BATON ROUG	NSERVATION INING DIVISI 3RD STREET GE, LA 70802	ON				ни и и и и и и и и и и и и и и и и и и
Date: Thursday, November 16, 2023 Time of Arrival: 12:00 PM Time of Departure: 1:45 PM Inspector Name(s): Sarah Hitchcock Sarah Hitchcock Sarah Hitchcock Sarah Hitchcock										18 date
Other personnel on site: J. Bradley, R. Broussard, Control Room Personnel, Walker Hill										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 65 Degrees, Overcast, Wind NNE at 3 mph										
Any planned work for today: Check pressures/observe bubbling locations										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central	CL 11-16 (east side of Central	Location 9 (Water location between PPG 2 and	Yellow Rock Wells	Cavern Well 2	Central Lake	Flowlines (all brine and oil
				Lake)	Lake)	PPG 4)	Production		Bubbling Locations)	flowlines)
NOTES: 1) Walker Hill is on location to begin drilling groundwater monitoring wells. 2) A gate has been installed behind the control room for additional security/restriction of access to the field.		Pad is dry.	Inj rate is 319 gpm; Minor bubbling alongside casing	Oil contained by sorbent boom. Boom has been replaced recently.	Minimal bubbling near bulkhead.	Multiple bubbling locations, but all very minimal.	SN 110159 (SWD) tbg - 180, csg - 0; SN 109963 (SWD) tbg - 0, csg - 90; SN 209459 (Producer) tbg - 30, csg - 60		No airboat ops today	
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	N/A	N/A	68	N/A	N/A	N/A		255.5		
Casing Pressure (if applicable)	162	N/A	429	N/A	N/A	N/A		401.9		
Bubbling?	No	No	Yes	Yes	Yes	Yes				
Sheen?	No	No	No	No	No	No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	No	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				
1	1			1		1	1	1	1	1