

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, November 20, 2023 Time of Arrival: 8:20 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Lindy Aultman [Tunner] Vance Hill [Yellowrock] Captain Richard {Stan's Airboats]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 68* to 74* Cloudy SE 12 mph

Any planned work for today: Check Bubbling site's - Check Cavern Well Pressure's - Check on some Pressures on some Yellowrock Wells - Inspect site for any adnormal signs

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Cavern Well 2	Cavern Well 2a	Cavern Well 20	CL-3,4,5.6.9.24	Yellowrock Wells	
location description):				(near BW-22, west						
				side of Central				(Central Lake		
				Lake)				bubbling site)		
Ride in Airboat to check those bubbling										
sites on water. Also check some Cavern well										
pressures & Yellowrock Wells. ERM								These bubblings		
has a waterwell driller on site drilling								sites were active @		
monitoring wells. Bubbling								time of inspection.		
activity is less today than has been in								The other bubbling		
previous inspections. 11/06/23								sites recorded on		
								Site Map were	#1012 55 psi tubing	
									S-7 180 psi tubing	
		Pad dry	313 gpm injection					inspection today.	S-4 0 psi tubing	
Photos taken? (save to F: drive)	no			no						
Tubing Pressure (if applicable)	160 psi		70 psi		258 psi	15 psi	557 psi			
Casing Pressure (if applicable)			430 psi		407 psi					
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						