INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, November 27, 2023 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Randy Broussard [Westlake] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 45* to 51* Clear/Sunny NNE 9 mph Any planned work for today: Same as pass Inspections										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	Cavern Well 2	Cavern Well 2A	Cavern Well 4	Cavern Well 20	CL-3,4,5 & 24	
(location description):										
									Central Lake	Central Lake
On Inspection I Observed that the bubbling site's that were bubbling were less intense than pervious inspections. Asked Randy Broussard if he could get an updated Video of CL-1 to have a history of that bubbling site. Stopped by Walker-Hill waterwell drilling Rig & there was no personal around @ time of inspection.		Pad Dry not able to see bubbles	276 gpm injection						These site's were bubbling @ time inspection	All other Bubbling site's in Central Lake site were inactive @ time of inspection
Photos taken? (save to F: drive)				yes						
Tubing Pressure (if applicable)	157 psi		72 psi		259 psi	12.3 psi	257 psi	521 psi		
Casing Pressure (if applicable)			356 psi		410 psi		265 psi			
Bubbling?				yes					yes	
Sheen?				yes					no	
Oil?				yes					no	
Odor?				yes					no	
Any new remedial work?				no					no	
Any impact to vegetation?				no					no	
Any impact to wildlife?				no					no	