

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, December 11, 2023 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Randy Broussard [Westlake] Captain Gavin [Stan's Airboats] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 42* to 56* Sunny ENE 4 mph

Any planned work for today: Check Bubbling site's, some Cavern Well pressures & some Well Pressure's on Yellowrock's Wells



Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL- 3,4,5,9 & 24	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
(location description):				(near BW-22, west						
				side of Central						
				Lake)						
Westlake had ERM taking some Gas samples from the bubblings site's.										
Walker-Hill People were Not on site @					Were active					
time of inspection.					bubblings site's					
					today during					
					inspection & all					
					other CL bubblings					
					site's were inactive					#1012 60 psi tubing
		Pad has fluid on it			@ time of inspetion					S-7 180 psi tubing
		today	318 gpm		today.					S-4 0 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	153 psi		71 psi			238 psi	12.5 psi	234 psi	555 psi	
Casing Pressure (if applicable)			431 psi			440 psi		243 psi		
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					