INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, December 18, 2023 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Kevin LaVergne [Westlake] Captain Gavin [Stan's Airboat's] Vance Hill [Yellowrock] Charles Trahan {ERM/Walker-Hill] Weather Conditions (Temp/Wind Speed/Direction, etc.): 54* to 63* Sunny NNW 6 mph Any planned work for today: Inspect Bubbling site's, Check some Cavern Well Pressure's and Check some Yellowrock tubing pressure's.										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central	CL-3,4,5,6,9 & 24 (Central Lake	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
				Lake)	Bubbling sites)					
Checked on Walker-Hill drilling the MW-2 700', Charles Trahan with ERM stated that they were in the 600'+ area and would be at TD today. No other work was pending today		Pad has fluid on it			Were active at time					
		and there is bubbling action			of inspection & all other bubbling					#1012 60 psi tubing S-7 180 psi tubing
		today	313 gpm injection		site's were inactive					S-4 0 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	151 psi		72 psi			247 psi	9.3 psi	244 psi	527 psi	
Casing Pressure (if applicable)			427 psi			571 psi		253 psi		
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					