Weather Conditions (Temp/Wind Speed/Dire	ection, etc.):	9:05 ce Hill {yellowrock] G 52* to 62* Windy/R ne Cavern Wells pres:	INJE B AM arvin w/Stan's Airboa ainy SE 19 mph		NSERVATION NING DIVISIO 3RD STREET 3E, LA 70802 2:0	ON				The second
Inspection locations: (location description):	Cavern 6X			CL-1 (near BW-22, west side of Central	Cavern Well 2	Cavern Well 2a	Cavern Well 4	CL-3,4,5,9 & 24	Cavern Well 20	Yellowrock
Checked on ERM/Walkerhill well services. Walkerhill was grouting the 500' MW-2 The Bubbling site's that are still active are not as intense as pior inspections.		Bubbling on the pad area of 7a	288 gpm injection	Less Oil @ this location today				All other Bubbling site's were not active @ time of Inspection.		#1012 60 psi tubing S-7 180 psi tubing S-4 0 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	146		64		250 psi	4.46 psi	246 psi		534 psi	
Casing Pressure (if applicable)			489		629 psi					
Bubbling?		yes	yes	yes				yes		
Sheen?				yes				no		
Oil?				yes				no		
Odor?				no				no		
Any new remedial work?				no				no		
Any impact to vegetation?				no				no		
Any impact to wildlife?				no						