Sector Sector		
000	OF CONSERV	MON P

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location: Sulphur Mines Dome

Date: Monday, January 22, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:20 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock] Captain Gavin w/Stain's Airboats

Weather Conditions (Temp/Wind Speed/Direction, etc.): 53* to 67* Mostly Cloudy ESE 16 mph

Any planned work for today: Check Bubblings site's, some Cavern Well pressures, check some of Yellowrock Well pressures & check on some of the contractors working on the Dom

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-3,4,5,6,9 & 24	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
(location description):				(near BW-22, west						
				side of Central	(east side of Central					
				Lake)	Lake)					
ERM/Walker-Hill working on MW-3 700'										
Well & they were grouting Well to top of										
plug to 240' or 250'.										
Yellowrock has a Workover Rig on Well										
#990 to Recomplete to a higher production										
zone. Also checked										
the area where some weather oil has been					All other bubbling					
seeping into Saltlake {check past logs on					site's were inactive					#1012 60 psi tubing
Location] video sent to Baton Rouge'		Pad dry @ time of			@ time of					S-7 180 psi tubing
		inspection.	injecting 319 gpm		inspection today					S-4 0 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	144 psi		71 psi			250 psi	3.24 psi	248 psi	550 psi	
Casing Pressure (if applicable)			432 psi			450 psi				
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					