INSPECTION FORM   OFFICE OF CONSERVATION   INJECTION & MINING DIVISION   INJECTION & MINING DIVISION   617 NORTH 3RD STREET   BATON ROUGE, LA 70802   Location: Sulphur Mines Dome   Date: Monday, January 29, 2024 Time of Arrival: 9:00 AM   Inspector Name(s): Billy Carnes   Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock] Captain Gavin[stari Airboats] Mathew Colvin [Tunner Cont.]   Weather Conditions (Temp/Wind Speed/Direction, etc.): 49 * to 62* Sunny NNE 5 mph										File and the second se
Any planned work for today: Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL-3,4,5,6,9,24,28	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
				side of Central Lake)						
ERM/Walker-Hill Personal were not on site @ time of inspection. Josh Bradley reposted a new bubbling site & recorded it bubbling. New bubbling site CL-28 by MW-2 500' Well										
		Pad dry not able to see bubbling	321 gpm injection	still bubbling Looks the same as the last inspection	Still bubbling @ time of inspection all other bubbling sites were inactive					#1012 60 psi tubin S-7 180 psi tubing S-4 0 psi tubing
Photos taken? (save to F: drive)	-		S21 gpm injection	no	sites were mactive					3-4 0 psi tubing
Tubing Pressure (if applicable)	143 psi		71 psi			254 psi	2.97 psi	251 psi	555 psi	
Casing Pressure (if applicable)			432 psi			452 psi				
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						
	<b>_</b>							<b> </b>		