INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, February 5, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Alex Harman [Westlake] Vance Hill [Yellowrock] Captain Gavin [Stan's Airboat] Weather Conditions (Temp/Wind Speed/Direction, etc.): 54* to 62* NNW 18 mph Any planned work for today: Check Bubbling site's, Check some Cavern Well Pressure's and Check on some Yellowrock Tubing Well pressure's											
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 20	CL-3,4,5,6,24.28 (Central Lake bubbling site)	Yellowrock		
ERM/Walker-Hill was working on MW-3 500' & the MW-1 500' Airboat Inspection in Central Lake bubbling site's.		Bubbling on Pad						All other bubbling were inactive @	#1012 60 psi tubing S-7 160 psi		
		today [fluid on pad]	314 gpm					time of inspection.	S-4 0 psi		
Photos taken? (save to F: drive)											
Tubing Pressure (if applicable)	194 psi		69 psi		247 psi	2.62 psi	417 psi				
Casing Pressure (if applicable)			429 psi		609 psi						
Bubbling?		yes		yes				yes			
Sheen?				yes				no	ļ		
Oil?				yes				no			
Odor?				yes				no			
Any new remedial work?				no				no			
Any impact to vegetation?				no				no			
Any impact to wildlife?				no				no			
			1	1	1	1	1	1			