INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, February 19, 2024 Time of Arrival: 8:30 AM Time of Departure: 11:00 AM Inspector Name(s): Billy Carnes Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock] Capt. Gavin [Stan's Airboats] Weather Conditions (Temp/Wind Speed/Direction, etc.): 46* to 60* Sunny SSW 6 mph Any planned work for today: Check bubbling site's, Check some Cavern Well Pressures, Check some Yellowrock Well pressures & check on ERM/Walker-Hill MW drillers										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL-3,4,5,6 24	Cavern 2	Cavern 2a	Cavern 4	Cavern 20	Yellowrock
(location description).				side of Central	still bubbling					
ERM/Walker-Hill working on the MW 3 700' well [moving off] Westlake was working on a Pipe repair		no bubbling visable today pad dry [no fluid]	331 injecting gpm	Still bubbling with a trace of Oil now	all other bubbling sites were inactive @ time of inspetion					#1012 60 psi tubing S-7 160 psi tubing S-4 40 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	145 psi tubing		70 psi			248 psi	2.58 psi	254 psi	483 psi	
Casing Pressure (if applicable)			430 psi			705 psi				
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				no	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					