(ALE	ENT OF HARD	
ana	CONSERVISION &	

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location: Sulphur Mines Dome

 Date:
 Monday, February 26, 2024
 Time of Arrival:
 9:05 AM
 Time of Departure:
 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Deann Chapman [Westlake] Vance Hill [Yellowrock] Capt. Gavin [Stan's Airboats]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 67* to 74* Party Cloudy SSW 14

Any planned work for today: Check Bubblings site's, some Cavern Wells & some Yellowrock Wells

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-3,4,5,6 24	Cavern 2	Cavern 2a	Cavern 4	Cavern 20	Yellowrock
(location description):										
On Inspection I observed Oil or a Tar like										
substance between CL-3 & CL-24 that look										
like it had belch up because of the oiling on										
the vegetation in that approximate 10'										
radius area. { No Bubbling action where the tar/oil is] Westlake has placed										
Absorbent boom around the affect area										
and will collect samples. Baton Rouge I &					All other CL					114042 CO
M office will be updating pictures on report		Pad dry - no visible			bubbling site's were inactive today					#1012 60 psi tubing S-7 40 psi tubing
spreedsheet.		bubbling	320 gpm injecting		during inspection					S-4 0 psi tubing
Photos taken? (save to F: drive)										p
Tubing Pressure (if applicable)	148 psi		71 psi			253 psi	2.50 psi	250 psi	505 psi	
Casing Pressure (if applicable)			431 psi			735 psi				
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				no	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					