Weather Conditions (Temp/Wind Speed/Dir	Time of Arrival: ergne [Westlake] Van ection, etc.): obling site's Check s	nce Hill [Yellowrock] (71* to 75* Cloudy S	INJI 5 AM Capt. Gavin [Stan's Ai E 10 mph	ECTION & MI 617 NORTH BATON ROUG Time of Departure rboats]	INSERVATION INING DIVISIO 3RD STREET GE, LA 70802					The second
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-3,4,5,6 24	Cavern 2	Cavern 2a	Cavern 4	Cavern 20	Yellowrock
The Oil/Tar seep between CL-3 & CL-24 Looked the same as prior inspection.		Pad dry, no bubbling seen	342 gpm injection	Bubbling and oil sheen look the same as prior inspections	All other CL bubbling site's were inactive @ time of inspection today					#1012 60 psi tubing S-7 40 psi tubing S-4 0 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	151 psi		73 psi			249 psi	2.42 psi	245 psi	524 psi	
Casing Pressure (if applicable)			431 psi			775 psi				
Bubbling?				yes	yes					
Sheen?				yes	no					
Dil?				yes	no					
Ddor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
							1	1	1	1
Any impact to wildlife?				no	no					