INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, March 18, 2024 Time of Arrival: 11:40 PM Time of Departure: 1:15 PM Inspector Name(s): Sarah Hitchcock Other personnel on site: K. Lavergne, R. Broussard, Control Room Personnel, Turner Industries Weather Conditions (Temp/Wind Speed/Direction, etc.): 64 Degrees, Sunny, Wind N at 15 mph Any planned work for today: Check pressures/observe bubbling locations										The second
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	CL 11-16	Location 9 (Water location	Yellow Rock Wells	Cavern Well 2	Central/Salt Lakes	Flowlines
				side of Central Lake)	(east side of Central Lake)	between PPG 2 and PPG 4)	Two SWDs and One Production		(Central Lake Bubbling Locations)	(all brine and oil flowlines)
NOTES:		Pad is dry.	Inj rate is 314 gpm		Minimal bubbling near bulkhead.	Multiple bubbling locations, but all very minimal.	SN 110159 (SWD) tbg - 40, csg - 0; SN 109963 (SWD) tbg - 5, csg - 280; SN 209459 (Producer) tbg - 40, csg - 70		Airboat noted nothing different at any of the bubbling locations in Central or Salt Lakes	
Photos taken? (save to F: drive)	No	No	No	No	No	No				
Tubing Pressure (if applicable)	N/A	N/A		N/A	N/A	N/A		249		
Casing Pressure (if applicable)	162	N/A		N/A	N/A	N/A		653		
Bubbling? Sheen?	No No	No No	No No	Yes (Minor) No	No (Very Windy) No	Yes No				
Oil?	No	No	No	Yes	No	No				
Odor?	No	No	No	No	No	No				
Any new remedial work?	No	No	No	No	No	No				
Any impact to vegetation?	No	No	No	No	No	No				
Any impact to wildlife?	No	No	No	No	No	No				