Location: Sulphur Mines Dome Date: Monday, March 25, 2024	INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM									The second
Inspector Name(s): Billy Carnes										
Other personnel on site: Patrick Tucker [Westlake] Vance Hill [Yellorock] Capt. Gavin [Stan's airboats]										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 71* to 73* Windy Cloudy with some rain										
Any planned work for today: Inspect bubbling site's, check some Cavern Well pressure's & check tubing pressure's on some Yellowrock Wells										
Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-3,4,5,6,18 & 24	Cavern 2	Cavern 2a	Cavern 4	Cavern 20	Yellowrock
(location description):										
Yellowrock has a Workover rig on Well #1030 and ERM/Walker-Hill is demobing equipment & roll off boxes off site										
				Site looks the same	-					#1012 60 psi tubing S-7 50 psi tubing
		fluid on pad today	334 gpm injection	as past inspections	of inspection					S-4 0 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	169 psi		71 psi			252 psi	2.81 psi	249 psi	449 psi	-
Casing Pressure (if applicable)			430 psi			332 psi				
Bubbling? Sheen?		yes no		yes yes	yes no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no		1			
Any impact to vegetation?		no		no	no		1			
Any impact to wildlife?		no		no	no					