INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, April 1, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Alex Harman [Westlake] Vance Hill [Yellowrock] Capt. Richard [w/Stan's Airboats] Meather Conditions (Temp/Wind Speed/Direction, etc.): 73* to 78* 5 13 mph Cloudy Any planned work for today: Check Bubblings site, Check some Cavern Well pressures & check some Yellowrock Tubing pressure's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-3,4,5,6,17,18,2	Cavern 2	Cavern 2a	Cavern 4	Cavern 20	Yellowrock
· · · ·										
Yellowrock had a workover Rig on Well # 1030										
		Pad dry no bubbling notice	318 gpm injection		All other CL bubbling sites were inactive today @ time of inspection					#1012 60 psi tubing S-7 50 psi tubing S-4 0 psi tubing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	174 psi		70 psi			252 psi	2.81 psi	249 psi	449 psi	
Casing Pressure (if applicable)			431 psi			332 psi				
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					