INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, April 15, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: DeAnn Chapman [Westlake] Pelican Surveying, Capt. Clay [Stan's Airboat's] Weather Conditions (Temp/Wind Speed/Direction, etc.): 73* to 78* Cloudy S 15 mph Any planned work for today: Check bubbling site's, check Cavern Well tubing pressures Some Yellowrock Well tubing pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-3,4,5,6,17,18,2 (Central Lake bubbling site)	Cavern Well 2	Cavern 2a	Cavern 20	Yellowrock	
Westlake has wireline on Cavern Well 7b and is getting Cavern wells 6x 20 ready for Wireline work		Pad dry not able to see bubbling	319 gpm injecting	still bubbling but site has less oil	The other Bubbling site's in Central Lake were not active during the Inspection			Flowing 106 gpm outflow to depressure Cavern for wireline work	#1012 60 psi tubing S-7 55 psi S-4 0 psi	
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	177 psi		71 psi			240 psi	2.34 psi			
Casing Pressure (if applicable)			427 psi			600 psi				
Bubbling?				yes	yes					
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						