TUNI OF MAN	INSPECTION FORM OFFICE OF CONSERVATION							8.0 Mg	IT IN ALL	AN
									A STATE OF THE STATE	
INJECTION & MINING DIVISION 617 NORTH 3RD STREET										RIV No.22 River No.22 Anter No.22443
										The start
BATON ROUGE, LA 70802										
Location: Sulphur Mines Dome										
Date: Monday, April 22, 2024	Time of Arrival: 8:30 AM			Time of Departure: 1:00 PM					DVX No. 23	
Inspector Name(s): Billy Carnes								1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		A CAL
	oussard [Westlake] Ca	pt. Richard [Stan's Ai	rboats] Vance Hill [Y	ellowrock]					A CONTRACT OF A	and starting
Weather Conditions (Temp/Wind Speed/Di	rection, etc.):	58* to 69* Sunny N	NE 10 mph					A TEL	A dece	
	bbling site's, some Yel	lowrock Well tubing	pressures & some W	estlake cavern well p	resures			Ser.	A CINE	
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	CL-3,4,5,6,21,24	Yellowrock
Lonquist & Walker-Hill is installing or drilling holes for the Deformation Moritoring Devices.										
		Pad dry - no bubbling seen	335 gpm injection						All other bubbling site's were inactive @ time of inspection	#1012 60 psi tubing S-7 55 psi tubing S-4 8 psi Tubing
Photos taken? (save to F: drive)	666 psi		67 psi		243 psi	2.42 psi	245 psi	619 psi		
Tubing Pressure (if applicable) Casing Pressure (if applicable)			427 psi		620 psi	2.42 psi	243 psi	013 h2i		
Bubbling?			727 p31	yes	020 p3	1		1	yes	
Sheen?				yes					no	
Oil?				yes					no	
Odor?				yes		1		1	no	
Any new remedial work?				no		1		1	no	
Any impact to vegetation?				no		1			no	
Any impact to wildlife?				no					no	
	1	1	1	1	1	1	1	1	1	<u> </u>