

INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Tuesday, April 30, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Capt. Gavin [Stan's Airboats] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 58* to 65* Sunny NNE 10 mph

Any planned work for today: Check bubbling site's, Some Cavern Well tubing/casing pressures and some Yellowrock Well tubing/casing pressures

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1	CL-3,4,5,6,24	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
(location description):				(near BW-22, west	3, .,0,0,- /					
				side of Central	(Central Lake					
					bubbling site's)					
					,					
Yellowrock had a Workover Rig on #1030										
										#1012 60 psi tubin
					All other bubbling					S-7 55 psi tubing 0
		fluid on pad today		site has less oil in it						psi casing
		able to observed		than in past	inactived @ time					S-4 5 psi tubing 22
		bubbling on pad	346 gpm injection	inspections	of inspection					psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	668 psi		70 psi			239 psi	2.54 psi	668 psi		
Casing Pressure (if applicable)			427 psi			680 psi			678 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					