A ORCE CA CONCERNMENT &	

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802



Location:	Sulphur	Mines	Dome
-----------	---------	-------	------

Date: Monday, May 6, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Randy Broussard [Westlake] Capt. Gavin [Stain's Airboats] Shannon [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 76\* to 82\* Partly Cloudy SSE 14 mph

Any planned work for today: Check bubbling site's some Cavern Well pressures & some of Yellowrock well pressures

Inspection locations:	Cavern 6X	Cavern Well 7A	Cavern Well 7B		CL 3,4,5,6,24	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
(location description):				(near BW-22, west						
					Central Lake					
				Lake)	bubbling site's					
General Comments:										#1012 30 psi tubing 60 psi casing
					All other past bubbling site's					S-7 60 psi tubing 0
		Pad still has fluid		Still bubbling with	were inactive today	,				psi casing S-4 5 psi tubing 205
		on it today	362 gpm injection	trace of OIL	during inspection.	·				psi casing
		on it today	Soz Spin injection		during inspection.					paredaning
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	669 psi		69 psi			238 psi	2.30 psi	235 psi		
Casing Pressure (if applicable)			423 psi			709 psi			708 psi	
Bubbling?		yes		yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					