Weather Conditions (Temp/Wind Speed/Dir	Time of Arrival: ussard [Westlake] Va ection, etc.): ubling site's, some Cav	nce Hill [Yellowrock} 81* to 88* Sunny SE	DAM Capt. Richard {Stan's	-	NSERVATION NING DIVISIO 3RD STREET iE, LA 70802					En
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	CL-bubbling spots	Yellow rock
				side of Central Lake)					3,4,5,6,9,19,21,23,2 4	
Operator is going to change out the absorb boom @ CL-1 later today or this week.		Fluid on pad bubbling noticed	335 gpm injection	Still bubbling with a small oil sheen, Bubbling & oil is less intense than passed inspections.					all other CL bubbling site's were inactived today @ time of inspection.	#1012 30 psi tubing 60 psi casing S-7 60 psi tubing 0 psi casing S-4 5 psi tubing 205 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	671 psi		69 psi		253 psi	2.03 psi	251 psi	671 psi		
Casing Pressure (if applicable)			427 psi							
Bubbling?		yes		yes					yes	
Sheen?		no		no					no	
Oil?		no		no					no	
Odor?		no		no					no	
Any new remedial work?		no		no					no	
Any impact to vegetation?		no		no					no	
Any impact to wildlife?		no		no					no	