INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Wednesday, May 29, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock] Capt. Richard [Stan's Airboats] Weather Conditions (Temp/Wind Speed/Direction, etc.): 78* to 82* sunny SSE 10 mph Any planned work for today: Check bubbling site's, Check some Cavern Well pressure's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
On inspection I observed that not much was happening with the bubbling site's today.		fluid on pad today was able to observe bubbling	Injecting 334 gpm		CL- 3,4,5,6,17,18,21,23, 24 were active @ time of inspection. All other bubbling site's were inactive @ time of inspection					#1012 60 psi tubing 60 psi casing S-7 50 psi tubing 0 psi casing S-4 5 psi tubing 190 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	669 psi		68 psi			261 psi	1.80 psi	259 psi	792 psi	
Casing Pressure (if applicable)			425 psi			776 psi				
Bubbling?		yes		yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					