

## INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, June 3, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Patrick Tucker [Westlake] Vance Hill [Yellowrock] Capt. Richard [Stan's Airboat's]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 79\* to 86\* partly cloudy S 13 mph

Any planned work for today: Check Bubbling site's, check some Cavern Well pressure's, check some of the Yellowrock Well pressure's



Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Westlake is changing out absorbed boom around CL-1										
					On inspection I					
					observed that CL-					
					3,4,5,6,21,23,24					#1012 60 psi tubing
					were active & the					60 psi casing
					other marked					S-7 50 psi tubing 0
		Observed bubbling			bubbling site's were					psi casing S-45
		on pad pad has			inactive today @					psi tubing 180 psi
		fluid on it today	Injecting 337 gpm		time of inspection.					casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	667 psi		71 psi			265 psi	1.99 psi	263 psi	806 psi	
Casing Pressure (if applicable)			428 psi			780 psi				
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				yes	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				nn	no					