INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION INJECTION & MINING DIVISION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, June 10, 2024 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM Inspector Name(s): Billy Carnes Other personnel on site: Jost Bradley [Westlake] Vance Hill [Yellowrock] Capt. Richard [Star's Airboats] Weather Conditions (Temp/Wind Speed/Direction, etc.): 83* to 89* Sunny NE 6 mpl: Any planned work for today: Check bubbling site's, look @ some of the Westlake Cavern Wells & check some pressure's on the Yellowrock Wells										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL-bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	Yellowrock
Westlake was changing out injection pumps on Cavern 7b		No bubbling observed pad dry today	482 gpm injection		CL- 3,4,5,6,717,18,21 & 24 observed bubbling during inspection, the other bubbling sites were inactived today during inspection.					#1012 45 psi tubing 45 psi casing S-7 50 psi tubing 0 psi casing S-4 5 psi tubing 180 psi casing #1017 300 psi tubing 310 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			91 psi			252 psi	2.19 psi	249 psi		
Casing Pressure (if applicable)	663 psi		408 psi			779 psi		282 psi	824 psi	
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						