TO THE	INSPECTION FORM						/	1975	And A	
	OFFICE OF CONSERVATION							See No. 21	No 12	Lave Participa
	INJECTION & MINING DIVISION									BW. No. 20
	617 NORTH 3RD STREET									Married States
BATON ROUGE, LA 70802										
Location: Sulphur Mines Dome										
Date: Monday, June 17, 2024	Time of Arrival:	9:00	DAM	Time of Departure:	1:0	0 PM			AW, No. 22	A A ANTINA
Inspector Name(s): Billy Carnes										200 (B) L
Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock] Capt. Gavin [Stan's Airboats]										
Weather Conditions (Temp/Wind Speed/Direction, etc.): 76* to 83* Rain in the morning then partly cloudy SSE 10 mph										
Any planned work for today: Check bubbling site's, Westlake Cavern Well pressures & some Yellowrock Well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	CL-bubbling Sites	Yellowrock
Westlake had no other work going on @ time of inspection.		Fluid on pad today	373 gpm injection	Still bubbling w/Oil					3,4,5,6,9,17,18,23 &	S-4 5 psi tubing 180 psi casing/ S-7 50 psi tubing 0 psi casing/#1012 45 psi tubing 45 psi casing/ #914 40 psi tubing 40 psi casing/ #997 0 psi tubing/ #871 0 psi vacuum/ SWD #987 256 psi t
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	659 psi		81 psi		251 psi	2.11	258 psi			
Casing Pressure (if applicable)			434 psi		511 psi			839 psi		
Bubbling?		yes		yes					yes	
Sheen?		no		yes					no	
Oil?		no		yes					no	
Odor?		no		yes					no	
Any new remedial work?		no		no					no	
Any impact to vegetation?		no		no					no	
Any impact to wildlife?		no		no					no	