INSPECTION FORM OFFICE OF CONSERVATION INJECTION & MINING DIVISION 617 NORTH 3RD STREET BATON ROUGE, LA 70802 Location: Sulphur Mines Dome Date: Monday, June 24, 2024 Time of Arrival: 9:00 AM Time of Departure: 12:30 PM Inspector Name(s): Billy Carnes Other personnel on site: Alex Hardman [Westlake] Capt. Gavin [Stan's Airboats] Vance Hill [Yellowrock] Weather Conditions (Temp/Wind Speed/Direction, etc.): 85* to 91* Party Cloudy SE 3 to 6 mph Any planned work for today: Check bubbling site's Cavern Well pressure's & some of Yellowrock Well pressure's										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	Cavern Well 2	Cavern Well 2a	Cavern Well 4	Cavern Well 20	CL bubbling site's	Yellowrock
No extra work being done today by Westlake or Yellowrock today during inspection.		Pad dry no bubbling observed during inspection	433 gpm injecting						CL-3,4,5,6,17,24 were active today all other bubling site's were inactive @ time of inspection.	#1012 40 psi tubing 40 psi casing #969 40 psi tubing 60 psi casing #1017 330 psi tubing & casing S-7 40 psi tubing 0 psi casing S-4 5 psi tubing 170 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			89 psi		258 psi	2.03 psi				
Casing Pressure (if applicable)	655 psi		431 psi		618 psi		255 psi	851 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				no						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						