Weather Conditions (Temp/Wind Speed/Dir Any planned work for today: Check bub	Monday, July 1, 2024 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM or Name(s): Billy Carues									
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL- bubbling sites	Cavern Well 2	Cavern Well 2a (Central Lake bubbling site)	Cavern Well 4	Cavern Well 20	Yellowrock Wells
Pelican Land Surveyor's are crosssectioning & working on the survey of the Containment Levee		Pad dry no bubbling observed	503 gpm injection		Observed CL- 3,4,5,6,17,21,& 24 had active bubbling @ time of inspection & observed the other bubbling sites were inactive @ time of inspection					Yellowrock is going to try to flow the #1012 well 6 hrs on the 7/2 & 7/3 if they can. #1012 50 psi tubing 50 psi casing #1017 310 psi tubing 320 psi casing S-7 50 psi tubing 0 psi casing S- 4 5 psi tubing 180 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	650 psi		90 psi			264 psi	2.07 psi	262 psi		
Casing Pressure (if applicable)			423 psi			633 psi			860 psi	
Bubbling?				yes	yes					
Sheen?				yes	no					
Oil?				yes	no					
Odor?				no	no					
Any new remedial work?				no	no					
Any impact to vegetation?				no	no					
Any impact to wildlife?				no	no					