Location: Sulphur Mines Dome Date: Wednesday, July 10, 2024 Inspector Name(s): Billy Carnes Other personnel on site: Josh Bradi	Time of Arrival: ey [Westlake] Vance		INJI E	ECTION & MI 617 NORTH BATON ROUC	NSERVATION INING DIVISIO 3RD STREET 5E, LA 70802					
Weather Conditions (Temp/Wind Speed/Direction, etc.): 85* to 91* Sunny NNE 4 mph										
Any planned work for today: Check bubbling site's, check some Cavern Well pressures & check some Yellowrock Well pressures										
Inspection locations: (location description):	Cavern 6X	Cavern Well 7A	Cavern Well 7B	CL-1 (near BW-22, west side of Central Lake)	CL bubbling site's	Cavern Well 2	Cavern Well 2a	Cavern Well 20	Cavern Well 4	Yellowrock
Longquist is working on Cavern 7b on trying to installing a fiber optic line downhole.		fluid on pad able to see bubbling	Longquist had equipment working on Well, Westlake was still injecting 518 gpm into well @ time of inspection	Still bubbling like	CL- 3,4,5,6,21 & 24 still bubbling @ time of inspection all others were inactive @ time of inspection					#1017 310 psi tubing 320 psi casing #1012 60 psi tubing 60 psi tubing S-7 50 psi tubing 0 psi casing S-4 5 psi tubing 150 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)	645 psi		103 psi			264 psi	1.99 psi			
Casing Pressure (if applicable)			431 psi			673 psi		870 psi	262 psi	
Bubbling?		yes		yes	yes					
Sheen?		no		yes	no					
Oil?		no		yes	no					
Odor?		no		yes	no					
Any new remedial work?		no		no	no					
Any impact to vegetation?		no		no	no					
Any impact to wildlife?		no		no	no					